

# Technical Bulletin



## How to Read a Coolant Analysis Report

Coolant analysis can identify the onset of several problems that can lead to potential cooling system failure. Corrosion, Supplemental Coolant Additive (SCA) deficiencies or excesses and inadequate freeze point protection are just a few of the many destructive conditions that can cause major systems damage.

The Seakits Coolant Analysis Report is easy to read and offers detailed conclusions and maintenance recommendations that will enable you to reduce major repairs and increase equipment uptime, productivity and safety.

**Equipment and Coolant** information tells your lab when the sample was taken and how many miles/hours are on both the unit and the coolant. Referencing the **Lab Sample Number** indicates the lab location where testing was completed and will expedite any questions concerning the sample.

POLARIS analysts provide you with maintenance recommendations based on in-depth analysis, taking the guesswork out of interpreting coolant analysis results.

Adequate **Glycol** levels must be maintained to ensure proper freeze point protection. High glycol can cause additive drop out and decrease coolant life. A glycol range of 40% to 60% is recommended.

The **Current Sample** is listed first. As many as four preceding samples may also be included.

Adequate **pH** range is vital to corrosion inhibition and should remain between 7.5 and 11.0.

Gradual buildup of **Total Dissolved Solids (TDS)** such as inhibitor chemicals, silicates, contaminants and water hardness compounds can lead to water pump leakage. TDS levels should not exceed 4%. Should leakage occur, drain coolant and flush pump with tap water.

UNIT ID: PHL61 COOL SECOND ID:		COMPANY INFORMATION									
UNIT TYPE: COOLANT - CONVENTIONAL EG USED											
APPLICATION: RAILROAD											
ACCOUNT NUMBER		DATE SAMPLED		DATE RECEIVED		DATE COMPLETED		<b>OVERALL SEVERITY OF REPORT</b> based on comments, not individual flags			
TRACKING #:		MANUFACTURER/MODEL:		FLUID MFR:		FLUID TYPE:		MICRON RATING:		0 1 2 3 4 NORMAL AB NORMAL CRITICAL	
DATE SAMPLED: 10/23/07		DATE RECEIVED: 10/31/07		DATE COMPLETED: 11/05/07		MANUFACTURER/MODEL: 07153M09515		FLUID MFR: MTU		LAB # 180561	
DATE RECEIVED: 10/31/07		DATE COMPLETED: 11/05/07		MANUFACTURER/MODEL: 07153M09515		FLUID MFR: MTU		FLUID TYPE: POWER COOL PLUS 6000		LOCATION S	
DATE COMPLETED: 11/05/07		MANUFACTURER/MODEL: 07153M09515		FLUID MFR: MTU		FLUID TYPE: POWER COOL PLUS 6000		MICRON RATING: 15		ANALYST EFN	
MANUFACTURER/MODEL: 07153M09515		FLUID MFR: MTU		FLUID TYPE: POWER COOL PLUS 6000		MICRON RATING: 15		FILTER TYPE: FULLFLOW			
FLUID MFR: MTU		FLUID TYPE: POWER COOL PLUS 6000		MICRON RATING: 15		FILTER TYPE: FULLFLOW		SUMP CAPACITY: 00065			
FLUID TYPE: POWER COOL PLUS 6000		MICRON RATING: 15		FILTER TYPE: FULLFLOW		SUMP CAPACITY: 00065		HYD SYSTEM PRESSURE: 0			
MICRON RATING: 15		FILTER TYPE: FULLFLOW		SUMP CAPACITY: 00065		HYD SYSTEM PRESSURE: 0		FLUID ADDED:			
FILTER TYPE: FULLFLOW		SUMP CAPACITY: 00065		HYD SYSTEM PRESSURE: 0		FLUID ADDED:					
SUMP CAPACITY: 00065		HYD SYSTEM PRESSURE: 0		FLUID ADDED:							
HYD SYSTEM PRESSURE: 0		FLUID ADDED:									
FLUID ADDED:											
COOLANT ANALYSIS REPORT - 877-458-3314											
COMMENTS: Total hardness and chloride have increased; Total Hardness is at a SIGNIFICANT level; Chloride is at a SIGNIFICANT level; This is most likely due to a source water problem; All other levels are all right; Watch to be sure this level does not increase; Resample in 60 days; Unit hours/miles conflicts with time from previous sample;											
CORROSION METALS - PPM			SCALE POTENTIAL PPM			CORROSION INHIBITORS - PPM			VISUALS		
SAMPLE #	ALUMINUM	COPPER	SILICON	MAGNESIUM	PHOSPHORUS	MOLYBDENUM	POTASSIUM	SODIUM	IRON	CHLORIDE	OTHER
1	4	0	4	0	0	0	22	0	89	107	9
2	5	0	5	0	0	1	19	1	88	113	10
3	8	0	1	0	0	0	31	2	97	120	2
SAMPLE #	DATE RECEIVED	UNIT	CHG	CHG	*F	*F	PH	TDS	SCA	CA	NA
1	07/06/07	860	U	U	32	212	0	8.6	55	3550	6720
2	07/24/07	1117	U	U	32	212	0	8.5	51	3520	6650
3	10/23/07	647	N	N	32	212	0	8.4	84	4040	7630

Data Analyst Initials

Corrosion occurs when buffers are no longer able to counter acid formation due to thermal degradation.  
**Typical Corrosion Product Sources:**  
**Iron**—liner, water pump, cylinder block/head  
**Aluminum**—radiator tanks, coolant elbows, piping, spacer plates, thermostat housings  
**Copper**—radiator, oil cooler, aftercooler, heater core  
**Lead**—radiator solder, oil cooler, aftercooler, heater core

Without adequate phosphate and borate **Buffers**, acids form, corrosion begins and rapid additive depletion will occur due to reduced pH values. Cylinder liner pitting will result.

**Silicon** protect cooling system metals. Sudden introduction of large amounts of antifreeze or SCAs high in silicates can clog radiators and heaters as well as restrict engine coolant passages. Rapid failure of water pump seals may result. For accurate silicate level evaluation, also test new antifreeze.

Excessive **Nitrite** levels can lead to solder corrosion. The **maximum** acceptable is 3333 ppm (parts per million).

An **SCA (Supplement Coolant Additive)** Level of 1.2 is the **minimum** required for adequate liner pitting protection. A level of 2.5 is ideal for extending coolant life.

Comments are advisory only and based on the assumption that the sample and data submitted are valid. Missing lube or unit time limits the evaluation. No warranty is expressed or implied.